THIS REPORT IS MADE IN ACCORDANCE WITH AND SUBJECT TO CONDITIONS ON THE REVERSE SIDE OF THIS PAGE This is not a structural damage report. Neither is this a warranty as to the total absence of wood-destroying insects.

OFFICIAL NORTH CAROLINA WOOD-DESTROYING INSECT INFORMATION REPORT

This is to report that a inspector employed by the below-named firm has carefully inspected readily accessible areas of the property located at the address below for wood-destroying insects. This report specifically excludes hidden areas and areas not readily accessible (see section 2 below) and the undersigned pest control operator has not made any inspection of such hidden areas or of such areas not readily accessible. This is not a warranty as to the total absence of wood-destroying insects or damage from same. The inspection described herein was made on the basis of visible evidence. This report is submitted without warranty, guarantee, or representation as to consealed evidence of infectation or damage or as to any future infectation.

1. Seller's Name(s)					
	Buyer's Name(s)Clinton Ebadi				
Address of Property 2125 Mariner Cir, Raleigh, NC, 27603-2665					
Structure(s) Inspected: A. Main Residence Onlyx B. Other					
FINDINGS					
2. Areas of the property which are deemed to be obstructed	ed or inaccessible: Insulation in crawl space area,				
floor, and wall covering. Attic not inspected due to limited access. Under deck inaccessible. Items under sunroom.					
Note: Certain areas of all structures are obstructed or inaccessible (see number	s 2 & 3 on reverse side for conditions governing this report).				
If there is evidence of a previous or an active infestation of su wooden members, it must be assumed that there is some damagency how slight. If this is the case, the structural integrity of this property of completing the report "infestation" means evidence of past or prestructure, or in or on debris under the structure.)	should be evaluated by a qualified building expert. (For the purpose				
3. Inspection revealed visible evidence of:	Locations of visible evidence of infestation:				
 □ A. Subterranean termites □ 1. Control measures were performed. □ 2. No control measures were performed. □ 3. Visible evidence of a previously treated infestation, which now appears to be inactive. 	Evidence in wood members under sunroom/deck.				
 □ B. Powder post Beetles □ 1. Control measures were performed. □ 2. No control measures were performed. □ 3. An infestation which now appears to be inactive. 					
 □ C. Old House Borers □ 1. Control measures were performed. □ 2. No control measures were performed. □ 3. An infestation which now appears to be inactive. 					
 □ D. Others □ 1. Control measures were performed. □ 2. No control measures were performed. □ 3. An infestation which now appears to be inactive. 					
☐ 4. No visible evidence of infestation from wood-destroy	ying insects was observed.				
5. The following conditions conducive to subterranean contact under sunroom/deck.	termites were noted on this property: Wood to ground				
IPM: Name Thereits & Dark & Dark	DCO Lie No. 1422 W. D-45				
IRM: Neuse Termite & Pest Control Inc. ddress: P.O. Box 446, Clayton, NC, 27528	PCO Lic No. 1443 PW Date 07/15/2019 Telephone: 919-553-9888				
ignature of Authorized Company Rep: White Tooks urchaser's signature is required on reverse side.	Title: Manager				

CONDITIONS GOVERNING THIS REPORT

- 1. This report is based on observations and opinions of the inspector. It must be noted that all buildings have some structural wood members which are not visible or accessible for inspection. It is not always possible to determine the presence of infestations without extensive probing and in some cases actual dismantling of parts of the structure being inspected. Extensive probing and dismantling have not been performed.
- This inspection and report are made on the basis of what was visible at the time of inspection. An opinion is not given on areas that were enclosed or not readily accessible: finished areas of ground level rooms (basement and split level); areas concealed by wall coverings, floor coverings, furniture, equipment, stored articles; or any portion of the structure in which inspection would necessitate tearing out or marring finished work. Furniture, appliances, equipment, insulation, fixed ceilings, etc. were not moved for inspection purposes.
- 3. Inspection did not include any area to which visible access would require the use of ladders or drills. Such areas are not considered to be readily accessible.
- 4. Detached garages, sheds, lean-tos, other buildings or fences on the property are not included in this inspection report unless specifically noted.
- 5. Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in this property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

REMARKS

This space should be used to clarify any statement made above.

This inspection is not for the purpose of reporting past, present, or future mold presence on the interior, exterior, or under the structure.

IT IS THE RESPONSIBILITY OF THE CLOSING AGENT TO OBTAIN PROPER SIGNATURES.

Purchaser's Signature(s)	 Date Acknowledged	

NEUSE TERMITE & PEST CONTROL, INC. Jennifer Baker **EXISTING STRUCTURAL CONDITIONS**

919-553-9888

SURVEY FINDINGS BASED ON VISUAL INSPECTION OF ACCESSIBLE AREAS

Termite Treatment W/Guarantee

Subterranean Termite Activity Exists as follows:

[] Active Termites

[] Swarmers

[] Swarmer Wings

[] Ground Infestation Spot Treatment


No Guarantee \$195 00

Visible Damage

[] Shelter Tubes

[] Swarmer Tubes

IX-INACTIVE TERMITE EVIDENCE /N-VISIBLE TERMITE DAMAGE X-ACTIVE TERMITE EVIDENCE (NOT TO BE REPAIRED BY NTPC.INC.) G-AREA OF THE STRUCTURE NOT COVERED BY REPAIR WDF-WOOD DECAY FUNGI **GUARANTEE PPB-POWDER POST BEETLES SW-STANDING** WATER EV-EXISTING VENTS A-ACCESS ALL CIRCLED NUMBERS-WOOD MOISTURE CONTENT **C-VISIBLE CONDENSATION READINGS**



INSPECTED BY:

DATE 7179 PURCHASER ACKNOWLEDGE